

03500.016081



PATENT

CJC

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:

MASASHI MIYAGAWA ET AL.

Appl. No.: 10/025,534

Filed: December 26, 2001

For: METHOD FOR MANUFACTURING
INK JET HEAD AND INK HEAD
MANUFACTURED BY SUCH
METHOD

U.S. Patent No.: 6,790,309 B2

Issued: September 14, 2004

Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450

Examiner: John T. Haran

Group Art Unit: 1733

Certificate
NOV 30 2004
of Correction

November 22, 2004

CERTIFICATE OF CORRECTION
UNDER RULES 322 AND 323

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form, in duplicate, is enclosed.

Accompanying this letter is a check for \$100.00 to cover the statutory fee for such Certificate of Correction.

11/24/2004 NNGUYEN2 00000165 6790309


01 FC:1811

100.00 0P

6 DEC 2004

Patentees' undersigned attorney may be reached in our New York office by telephone at (212) 218-2100. All correspondence should continue to be directed to our address given below.

Respectfully submitted,



John A. Krause
Attorney for Patentees
Registration No.: 24613

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
Facsimile: (212) 218-2200

NY_MAIN 464789v1

Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,790,309 B2

DATED : September 14, 2004

INVENTOR(S) : MASASHI MIYAGAWA ET AL.

Page 1 of 4

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 2

Line 39, "ryas" should read --rays--; and

Line 51, "component," should read --components,--.

COLUMN 3

Line 1, "soften" should read --softened--; and

Line 4, "movable" should read --a movable--.

COLUMN 4

Line 8, "ryas" should read --rays--.

COLUMN 5

Line 34, "process." should read --process;--.

COLUMN 7

Line 2, "contactness," should read --contact,--;

Line 18, "from of" should read --form of--;

Line 22, "dissolved" should read --being dissolved--; and

Line 65, "dried." should read --being dried.--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 6,790,309 B2

No. of add'l. copies
@ 30¢ per page



Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,790,309 B2

DATED : September 14, 2004

INVENTOR(S) : MASASHI MIYAGAWA ET AL.

Page 2 of 4

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 8

Line 18, "are is" should read --are--; and
Line 45, "catalyst" should read --a catalyst--.

COLUMN 9

Line 6, "a adhesive" should read --an adhesive--;
Line 14, "rays is" should read --rays are--; and
Line 63, "is irradiated" should read --are irradiated--.

COLUMN 10

Line 10, "this" should read --This--;
Line 11, "leave it" should read --is left--;
Line 32, "photo-sensitive" should read --photosensitive--;
Line 37, "any bonding strength occurs." should read --does any bonding strength occur--;
Line 44, "leave it" should read --is left--;
Line 56, "photo-sensitive" should read --photosensitive--; and
Line 66, "photo-sensitive" should read --photosensitive--.

COLUMN 11

Line 22, "rays is" should read --rays are--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 6,790,309 B2

No. of add'l. copies
@ 30¢ per page



Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,790,309 B2

DATED : September 14, 2004

INVENTOR(S) : MASASHI MIYAGAWA ET AL.

Page 3 of 4

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 12

Line 61, "photo-sensitive" should read --photosensitive--.

COLUMN 13

Line 6, "is irradiated" should read --are irradiated--;

Line 16, "left" should read --being left--;

Line 16, "3months," should read --3 months,--;

Line 40, "is irradiated" should read --are irradiated--;

Line 49, "left" should read --being left--; and

Line 61, "photo-sensitive" should read --photosensitive--.

COLUMN 14

Line 5, "photo-sensitive" should read --photosensitive--;

Line 9, "good enough." should read --well enough.--;

Line 12, "make" should read --promote--;

Line 12, "promoted" should be deleted; and

Line 54, "reaction progressed" should read --the reaction progress--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 6,790,309 B2

No. of add'l. copies
@ 30¢ per page



Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,790,309 B2

DATED : September 14, 2004

INVENTOR(S) : MASASHI MIYAGAWA ET AL.

Page 4 of 4

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 15

Line 38, "contactness" should read --contact--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 6,790,309 B2

No. of add'l. copies
@ 30¢ per page



Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,790,309 B2

DATED : September 14, 2004

INVENTOR(S) : MASASHI MIYAGAWA ET AL.

Page 1 of 4

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 2

Line 39, "ryas" should read --rays--; and

Line 51, "component," should read --components,--.

COLUMN 3

Line 1, "soften" should read --softened--; and

Line 4, "movable" should read --a movable--.

COLUMN 4

Line 8, "ryas" should read --rays--.

COLUMN 5

Line 34, "process." should read --process;--.

COLUMN 7

Line 2, "contactness," should read --contact,--;

Line 18, "from of" should read --form of--;

Line 22, "dissolved" should read --being dissolved--; and

Line 65, "dried." should read --being dried.--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 6,790,309 B2

No. of add'l. copies
@ 30¢ per page



Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,790,309 B2

DATED : September 14, 2004

INVENTOR(S) : MASASHI MIYAGAWA ET AL.

Page 2 of 4

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 8

Line 18, "are is" should read --are--; and
Line 45, "catalyst" should read --a catalyst--.

COLUMN 9

Line 6, "a adhesive" should read --an adhesive--;
Line 14, "rays is" should read --rays are--; and
Line 63, "is irradiated" should read --are irradiated--.

COLUMN 10

Line 10, "this" should read --This--;
Line 11, "leave it" should read --is left--;
Line 32, "photo-sensitive" should read --photosensitive--;
Line 37, "any bonding strength occurs." should read --does any bonding strength occur.--;
Line 44, "leave it" should read --is left--;
Line 56, "photo-sensitive" should read --photosensitive--; and
Line 66, "photo-sensitive" should read --photosensitive--.

COLUMN 11

Line 22, "rays is" should read --rays are--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 6,790,309 B2

No. of add'l. copies
@ 30¢ per page



DEC 6 2004

Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,790,309 B2

DATED : September 14, 2004

INVENTOR(S) : MASASHI MIYAGAWA ET AL.

Page 3 of 4

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 12

Line 61, "photo-sensitive" should read --photosensitive--.

COLUMN 13

Line 6, "is irradiated" should read --are irradiated--;
Line 16, "left" should read --being left--;
Line 16, "3months," should read --3 months,--;
Line 40, "is irradiated" should read --are irradiated--;
Line 49, "left" should read --being left--; and
Line 61, "photo-sensitive" should read --photosensitive--.

COLUMN 14

Line 5, "photo-sensitive" should read --photosensitive--;
Line 9, "good enough." should read --well enough.--;
Line 12, "make" should read --promote--;
Line 12, "promoted" should be deleted; and
Line 54, "reaction progressed" should read --the reaction progress--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 6,790,309 B2

No. of add'l. copies
@ 30¢ per page

Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,790,309 B2

DATED : September 14, 2004

INVENTOR(S) : MASASHI MIYAGAWA ET AL.

Page 4 of 4

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 15

Line 38, "contactness" should read --contact--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 6,790,309 B2

No. of add'l. copies
@ 30¢ per page

